

SELF SUPPORT GLAZING BARS

Fixing Instructions

When cutting the glazing bars to lengths allow a 60mm overhang into the gutter.

If self support glazing bars are being used with a wall plate, drill the glazing bar with an 8mm hole each side of the underside of the bar and 15mm from the end of the bar. Locate the glazing bars onto the previously positioned captive wall plate bolts. Ensure the glazing bars are parallel before tightening nuts.

If fixing to a timber wall plate/support drill and screw fix as appropriate.

Once the glazing bar bases are secure place the polycarbonate sheet in position before clipping the top caps into place. Ensure the top caps are fully clipped down. Silicon seal the butt joint between the glazing bar top cap and the wall plate.